

Machine Application Chart

Attachment	Type	Size/Model	Position	Travel		REQUIRED COMPONENTS			REFERENCE INFO.		
				STD	Req'd	Adapter & Hardware Assembly	Setting Gage	Control Valve	Mount Info. Dwg	Trip Brkt Mount Dwg	Remarks
170SA-1											
A70WSW2500	Warner Swasey	M2500	3rd	.688	2.750	No Req'd	170001	141600	170206	160256	Limited App.
A70WSW2500	Warner Swasey	M2500	4th	.625	2.437	No Req'd	170001	141600	170206	160256	Limited App.
A70WSW2530	Warner Swasey	M2530	3rd	.688	2.750	No Req'd	170012	141600	170210	160231	Limited App.
A70WSW2530	Warner Swasey	M2530	4th	.625	2.437	No Req'd	170012	141600	170210	160231	Limited App.
A70WM13/46	Wickman	1 3/4-6	4th	1.562	2.062	No Req'd	170012	141600	170209	160231	SEC 293 (1)
A70WM13/46	Wickman	1 3/4-6	5th	1.250	2.062	No Req'd	170012	141600	170209	160231	SEC 293 (1)
A70WM13/48	Wickman	1 3/4-8	5th	2.000	2.813	160305	170012	141600	170211	160231	(1)
A70WM13/48	Wickman	1 3/4-8	6th	1.750	2.813	160305	170012	141600	170211	160231	(1)
A70WM21/46	Wickman	2 1/4-6	4th	1.625	2.500	160305	170012	141600	170214	160231	SEC 393 (1)
A70WM21/46	Wickman	2 1/4-6	5th	1.250	2.500	160305	170012	141600	170214	160231	SEC 393 (1)
A70WM25/86	Wickman	2 5/8-6	4th	2.000	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A70WM25/86	Wickman	2 5/8-6	5th	1.750	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A70WM31/24	Wickman	3 1/2-4	3rd	2.000	2.313	160301	170012	141600	170209	160231	(1)
A70WM31/24	Wickman	3 1/2-4	4th	1.750	2.313	160301	170012	141600	170209	160231	(1)
A70WM31/46	Wickman	3 1/4-6	4th	2.000	1.500	160301	170012	141600	170211	160231	SEC 593 (1)
A70WM31/46	Wickman	3 1/4-6	5th	1.750	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A70WM41/84	Wickman	4 1/8-4				160301	170012	141600	170211	160231	
A70WM41/84	Wickman	4 1/8-4				160301	170012	141600	170211	160231	

1) Requires auxiliary cross slide motion for max clearance.

Machine Application Chart

Attachment	Type	Size/Model	Position	Travel		REQUIRED COMPONENTS			REFERENCE INFO.		
				STD	Req'd	Adapter & Hardware Assembly	Setting Gage	Control Valve	Mount Info. Dwg	Trip Brkt Mount Dwg	Remarks
172SA-1											
A72WSW2500	Warner Swasey	M2500	3rd	.688	2.750	No Req'd	170001	141600	170206	160256	Limited App.
A72WSW2500	Warner Swasey	M2500	4th	.625	2.437	No Req'd	170001	141600	170206	160256	Limited App.
A72WSW2530	Warner Swasey	M2530	3rd	.688	2.750	No Req'd	170012	141600	170210	160231	Limited App.
A72WSW2530	Warner Swasey	M2530	4th	.625	2.437	No Req'd	170012	141600	170210	160231	Limited App.
A72WM13/46	Wickman	1 3/4-6	4th	1.562	2.062	No Req'd	170012	141600	170209	160231	SEC 293 (1)
A72WM13/46	Wickman	1 3/4-6	5th	1.250	2.062	No Req'd	170012	141600	170209	160231	SEC 293 (1)
A72WM13/48	Wickman	1 3/4-8	5th	2.000	2.813	160305	170012	141600	170211	160231	(1)
A72WM13/48	Wickman	1 3/4-8	6th	1.750	2.813	160305	170012	141600	170211	160231	(1)
A72WM21/46	Wickman	2 1/4-6	4th	1.625	2.500	160305	170012	141600	170214	160231	SEC 393 (1)
A72WM21/46	Wickman	2 1/4-6	5th	1.250	2.500	160305	170012	141600	170214	160231	SEC 393 (1)
A72WM25/86	Wickman	2 5/8-6	4th	2.000	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A72WM25/86	Wickman	2 5/8-6	5th	1.750	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A72WM31/24	Wickman	3 1/2-4	3rd	2.000	2.313	160301	170012	141600	170209	160231	(1)
A72WM31/24	Wickman	3 1/2-4	4th	1.750	2.313	160301	170012	141600	170209	160231	(1)
A72WM31/46	Wickman	3 1/4-6	4th	2.000	1.500	160301	170012	141600	170211	160231	SEC 593 (1)
A72WM31/46	Wickman	3 1/4-6	5th	1.750	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A72WM41/84	Wickman	4 1/8-4				160301	170012	141600	170211	160231	
A72WM41/84	Wickman	4 1/8-4				160301	170012	141600	170211	160231	

1) Requires auxiliary cross slide motion for max clearance.

Machine Application Chart

Attachment	Type	Size/Model	Position	Travel		REQUIRED COMPONENTS			REFERENCE INFO.		
				STD	Req'd	Adapter & Hardware Assembly	Setting Gage	Control Valve	Mount Info. Dwg	Trip Brkt Mount Dwg	Remarks
173SA-1											
A73X	Warner Swasey	M2500	3rd	.688	2.750	No Req'd	170001	141600	170206	160256	Limited App.
A73X	Warner Swasey	M2500	4th	.625	2.437	No Req'd	170001	141600	170206	160256	Limited App.
A73X	Warner Swasey	M2530	3rd	.688	2.750	No Req'd	170012	141600	170210	160231	Limited App.
A73X	Warner Swasey	M2530	4th	.625	2.437	No Req'd	170012	141600	170210	160231	Limited App.
A73X	Wickman	1 3/4-6	4th	1.562	2.062	No Req'd	170012	141600	170209	160231	SEC 293 (1)
A73X	Wickman	1 3/4-6	5th	1.250	2.062	No Req'd	170012	141600	170209	160231	SEC 293 (1)
A73X	Wickman	1 3/4-8	5th	2.000	2.813	160305	170012	141600	170211	160231	(1)
A73X	Wickman	1 3/4-8	6th	1.750	2.813	160305	170012	141600	170211	160231	(1)
A73WM21/46	Wickman	2 1/4-6	4th	1.625	2.500	160305	170012	141600	170214	160231	SEC 393 (1)
A73WM21/46	Wickman	2 1/4-6	5th	1.250	2.500	160305	170012	141600	170214	160231	SEC 393 (1)
A73X	Wickman	2 5/8-6	4th	2.000	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A73X	Wickman	2 5/8-6	5th	1.750	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A73X	Wickman	3 1/2-4	3rd	2.000	2.313	160301	170012	141600	170209	160231	(1)
A73X	Wickman	3 1/2-4	4th	1.750	2.313	160301	170012	141600	170209	160231	(1)
A73X	Wickman	3 1/4-6	4th	2.000	1.500	160301	170012	141600	170211	160231	SEC 593 (1)
A73X	Wickman	3 1/4-6	5th	1.750	2.500	160301	170012	141600	170211	160231	SEC 593 (1)
A73X	Wickman	4 1/8-4				160301	170012	141600	170211	160231	
A73X	Wickman	4 1/8-4				160301	170012	141600	170211	160231	

1) Requires auxiliary cross slide motion for max clearance.